

TENDER FOR RELOCATION OF ONE GE FRAME 6 GAS TURBINE FROM EMBAKASI IN NAIROBI TO MUHORONI NEAR KISUMU: KGN-GT-12-2017

KenGen wishes to make the following clarification as sought by potential bidders on the above tender through clarification 2

ITEM	REQUESTED INFORMATION	COMMENT/CLARIFICATION
1	Details of unit's plant and content of plant.	Details of the Units plant is as was explained and Shown during the site Visit at Embakasi. Operation and maintenance manuals which give details of the various equipment are available. Same will be available for use by the successful bidder.
2	Age of plant	Plant Commissioned in February/ March 1999
3	Operating hours	38,041.5 hours as at November 2016.
4	Maintenance Conducted	Major inspection in 2006, Combustion inspection in 2010; Hot Gas path Inspection in 2014.
5	Who installed plant?	John Brown Engineering of Scotland
6	Who Commissioned plant	John Brown Engineering of Scotland
7	Documentation	<p>During dismantling the Contractor is expected to prepare drawings 'As Is' at Embakasi if necessary for Own use. Upon assembly at Muhoroni the Contractor shall prepare drawings 'As built', for handover to Employer.</p> <p>A performance test will be carried out as detailed in the tender Document to confirm status of plant. Available Commissioning records will be provided upon award of the Tender</p> <p>Provision of maintenance records not necessary for the purpose of tendering but they are available. Civil drawings are provided in the tender document. The Contractor is expected to come up with Construction drawings since loads are provided and this is part of the Project Engineering. Previous civil works drawings will be made available to successful bidder.</p>

ACKNOWLEDGEMENT OF ADDENDUM 1

We/I, the undersigned hereby certify that the addendum is an integral part of the document and the alterations set out in the Addendum have been incorporated in the tender proposal.

Signed.....

Tenderer.....